

HopeSource Pre-Trip Inspection Report

Date: 12/29/11

Vehicle # 296

Operator Bob W

Mileage 198,944

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment		
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield		✓
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil		
2) Coolant		
3) Transmission	✓	
4) Steering		
5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks: Rock chips in windshield

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

AW

HopeSource Pre-Trip Inspection Report

Date: 12-28-11

Vehicle # 296 Operator Scott S Mileage 198581

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	✓		• Radio/Cell Phone	✓	
• Interior Lights	✓		• Brakes	✓	
• Passenger Seat Condition	✓		• Parking Brake	✓	
• Emergency Equipment	✓		• Windshield	✓	
1) First Aid Kit	✓		• Headlights, Signals, 4-Ways	✓	
2) Fire Extinguisher	✓		• Tire/Wheel Condition	✓	
3) Reflections	✓		• Lug Nut Tightness	✓	
4) Strap Cutter	✓		• Body Condition	✓	
• Passenger Door Operations	✓		• Cycle W/C Lift	✓	
• Windshield	✓		• W/C Tiedowns & Accessories	✓	
Wipers/Washers & Fluid	✓		• Schedules	✓	
• Fans/Defrosters	✓		• Customer Service Forms	✓	
• Horn	✓		• Farebox	✓	
• Driver Seat & Belt	✓		• Fluids	✓	
• Mirrors	✓		1) Oil	Added	
			2) Coolant	4 oz	
			3) Transmission		
			4) Steering		
			5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

AW

HopeSource Pre-Trip Inspection Report

Date: 12-27/11

Vehicle # 296 Operator Scott S

Mileage 198455

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid		
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors		✓

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil		
2) Coolant		
3) Transmission	—	
4) Steering		
5) Brake		

Mechanical Defect Report

Defect # (see above) ✓

Remarks: missing small mirror at back of Bus

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

HopeSource Pre-Trip Inspection Report

Date: 12/23/11

Vehicle # 296

Operator Beno W

Mileage 198398

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil		
2) Coolant		
3) Transmission		
4) Steering		
5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

AWK

HopeSource Pre-Trip Inspection Report

Date: 12/20/11

Vehicle # 296

Operator AWW

Mileage 198161

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil	✓	
2) Coolant		
3) Transmission		
4) Steering		
5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

AWW

HopeSource Pre-Trip Inspection Report

Date: 12-20-2011

Vehicle # 295

Operator Tom Mace

Mileage 198538

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield		
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil ✓		
2) Coolant ✓		
3) Transmission ✓		
4) Steering ✓		
5) Brake ✓		

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

AW

HopeSource Pre-Trip Inspection Report

Date: 12-19-11

Vehicle # 257 Operator L. Lee

Mileage 198292

	Ok	Defect
• Fluid Leaks Under Bus	/	
• Interior Lights	/	
• Passenger Seat Condition	/	
• Emergency Equipment	/	
1) First Aid Kit	/	
2) Fire Extinguisher	/	
3) Reflections	/	
4) Strap Cutter	/	
• Passenger Door Operations	/	
• Windshield	/	
Wipers/Washers & Fluid	/	
• Fans/Defrosters	/	
• Horn	/	
• Driver Seat & Belt	/	
• Mirrors	/	

	Ok	Defect
• Radio/Cell Phone	NA	
• Brakes	/	
• Parking Brake	/	
• Windshield	/	
• Headlights, Signals, 4-Ways	/	
• Tire/Wheel Condition	/	NA
• Lug Nut Tightness	/	
• Body Condition	/	
• Cycle W/C Lift	✓	NA
• W/C Tiedowns & Accessories	/	
• Schedules	/	
• Customer Service Forms	/	
• Farebox	/	
• Fluids	/	
1) Oil	/	
2) Coolant	/	
3) Transmission	/	
4) Steering	/	
5) Brake	/	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

~~W/C lift wouldn't deploy started working later in the day~~

Maintenance Disposition

Work Order # _____

Repairs Made _____

Monitor

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

ALW

HopeSource Pre-Trip Inspection Report

Date: 12-19-11

Vehicle # 296 Operator Scott S

Mileage 198038

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil		
2) Coolant		
3) Transmission		
4) Steering		
5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

AW

HopeSource Pre-Trip Inspection Report

Date: 12-16-11

Vehicle # 296 Operator Scott S

Mileage 197768

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	✓		• Radio/Cell Phone	✓	
• Interior Lights	✓		• Brakes	✓	
• Passenger Seat Condition	✓		• Parking Brake	✓	
• Emergency Equipment	✓		• Windshield	✓	
1) First Aid Kit	✓		• Headlights, Signals, 4-Ways	✓	
2) Fire Extinguisher	✓		• Tire/Wheel Condition	✓	
3) Reflections	✓		• Lug Nut Tightness	✓	
4) Strap Cutter	✓		• Body Condition	✓	
• Passenger Door Operations	✓		• Cycle W/C Lift	✓	
• Windshield	✓		• W/C Tiedowns & Accessories	✓	
Wipers/Washers & Fluid	✓		• Schedules	✓	
• Fans/Defrosters	✓		• Customer Service Forms	✓	
• Horn	✓		• Farebox	✓	
• Driver Seat & Belt	✓		• Fluids	✓	
• Mirrors	✓		1) Oil		
			2) Coolant		
			3) Transmission		
			4) Steering		
			5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

AW

HopeSource Pre-Trip Inspection Report

Date: 12-15-11

Vehicle # 296 Operator Scott S Mileage 197504

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	✓		• Radio/Cell Phone		
• Interior Lights	✓		• Brakes	✓	
• Passenger Seat Condition	✓		• Parking Brake	✓	
• Emergency Equipment	✓		• Windshield	✓	
1) First Aid Kit	✓		• Headlights, Signals, 4-Ways	✓	
2) Fire Extinguisher	✓		• Tire/Wheel Condition	✓	
3) Reflections	✓		• Lug Nut Tightness	✓	
4) Strap Cutter	✓		• Body Condition	✓	
• Passenger Door Operations	✓		• Cycle W/C Lift	✓	
• Windshield	✓		• W/C Tiedowns & Accessories	✓	
Wipers/Washers & Fluid	✓		• Schedules	/	
• Fans/Defrosters	✓		• Customer Service Forms	/	
• Horn	✓		• Farebox	/	
• Driver Seat & Belt	✓		• Fluids	/	
• Mirrors	✓		1) Oil		
			2) Coolant		
			3) Transmission		
			4) Steering		
			5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

AW

HopeSource Pre-Trip Inspection Report

Date: 12-14-11

Vehicle # 296 Operator L. Lee

Mileage 197410

	Ok	Defect
• Fluid Leaks Under Bus		
• Interior Lights		
• Passenger Seat Condition	/	
• Emergency Equipment	/	
1) First Aid Kit	/	
2) Fire Extinguisher	/	
3) Reflections	/	
4) Strap Cutter	/	
• Passenger Door Operations	/	
• Windshield		
Wipers/Washers & Fluid	/	
• Fans/Defrosters	/	
• Horn	/	
• Driver Seat & Belt	/	
• Mirrors	/	

	Ok	Defect
• Radio/Cell Phone	N/A	
• Brakes	/	
• Parking Brake	/	
• Windshield	/	
• Headlights, Signals, 4-Ways	/	
• Tire/Wheel Condition	/	*
• Lug Nut Tightness	/	
• Body Condition	/	
• Cycle W/C Lift	/	
• W/C Tiedowns & Accessories	/	
• Schedules	/	
• Customer Service Forms	/	
• Farebox	/	
• Fluids	/	
1) Oil	/	
2) Coolant	/	
3) Transmission	/	
4) Steering	/	
5) Brake	/	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Right front low tread

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

AW

HopeSource Pre-Trip Inspection Report

Date: 12-8-11

Vehicle # 296 Operator Scott S

Mileage 197086

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	✓		• Radio/Cell Phone	✓	
• Interior Lights	✓		• Brakes	✓	
• Passenger Seat Condition	✓		• Parking Brake	✓	
• Emergency Equipment	✓		• Windshield	✓	
1) First Aid Kit	✓		• Headlights, Signals, 4-Ways	✓	
2) Fire Extinguisher	✓		• Tire/Wheel Condition	✓	
3) Reflections	✓		• Lug Nut Tightness	✓	
4) Strap Cutter	✓		• Body Condition	✓	
• Passenger Door Operations	✓		• Cycle W/C Lift	✓	
• Windshield	✓		• W/C Tiedowns & Accessories	✓	
Wipers/Washers & Fluid					
• Fans/Defrosters	✓	X	• Schedules	✓	
• Horn	✓		• Customer Service Forms	✓	
• Driver Seat & Belt	✓		• Farebox	✓	
• Mirrors	✓		• Fluids	✓	
			1) Oil		
			2) Coolant	✓	
			3) Transmission		
			4) Steering		
			5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks: Heater very weak!
NOT warming up.

Maintenance Disposition

Work Order # _____

Repairs Made YARIMA TRANSIT HANDLING
REPAIRS VIA PUBLIC WORKS
SHOP.

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

AW

HopeSource Pre-Trip Inspection Report

Date: 12-7-11

Vehicle # 296 Operator L Lee

Mileage 196992

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	/		• Radio/Cell Phone	NA	
• Interior Lights	/		• Brakes	/	
• Passenger Seat Condition	/		• Parking Brake	/	
• Emergency Equipment	/		• Windshield	/	
1) First Aid Kit	/		• Headlights, Signals, 4-Ways	/	
2) Fire Extinguisher	/		• Tire/Wheel Condition	/	
3) Reflections	/		• Lug Nut Tightness	/	
4) Strap Cutter	/		• Body Condition	/	
• Passenger Door Operations	/		• Cycle W/C Lift	/	
• Windshield	/		• W/C Tiedowns & Accessories	/	
Wipers/Washers & Fluid	/		• Schedules	/	
• Fans/Defrosters	/	*	• Customer Service Forms	/	
• Horn	/		• Farebox	/	
• Driver Seat & Belt	/		• Fluids	/	
• Mirrors	/		1) Oil	/	
			2) Coolant	/	
			3) Transmission	/	
			4) Steering	/	
			5) Brake	/	

Mechanical Defect Report

Defect # (see above) *

Remarks: REAR CENTRAL FAN NOT WORKING

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

AW ✓

HopeSource Pre-Trip Inspection Report

Date: 12-6-11

Vehicle # 296 Operator Scott S

Mileage 196897

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	/		• Radio/Cell Phone	/	
• Interior Lights	/		• Brakes	/	
• Passenger Seat Condition	/		• Parking Brake	/	
• Emergency Equipment	/		• Windshield	/	
1) First Aid Kit	/		• Headlights, Signals, 4-Ways	/	
2) Fire Extinguisher	/		• Tire/Wheel Condition	/	
3) Reflections	/		• Lug Nut Tightness	/	
4) Strap Cutter	/		• Body Condition	/	
• Passenger Door Operations	/		• Cycle W/C Lift	/	
• Windshield	/		• W/C Tiedowns & Accessories	/	
Wipers/Washers & Fluid	/		• Schedules	/	
• Fans/Defrosters	/		• Customer Service Forms	/	
• Horn	/		• Farebox	/	
• Driver Seat & Belt	/		• Fluids	/	
• Mirrors	/		1) Oil		
			2) Coolant		
			3) Transmission		
			④ Steering		
			5) Brake		
				Added	
				1oz	
				of	
				fluid	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

** Monitor Power Steering Fluid*
RJR

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

AW

HopeSource Pre-Trip Inspection Report

Date: 12/5/11

Vehicle # 296 Operator Scott S

Mileage 196803

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus			• Radio/Cell Phone	/	
• Interior Lights	/		• Brakes	/	
• Passenger Seat Condition	/		• Parking Brake	/	
• Emergency Equipment	/		• Windshield	/	
1) First Aid Kit	/		• Headlights, Signals, 4-Ways	/	
2) Fire Extinguisher	/		• Tire/Wheel Condition	/	
3) Reflections	/		• Lug Nut Tightness	/	
4) Strap Cutter	X		• Body Condition	/	
• Passenger Door Operations	/		• Cycle W/C Lift		
• Windshield	/		• W/C Tiedowns & Accessories	/	
Wipers/Washers & Fluid	/		• Schedules	/	
• Fans/Defrosters	/		• Customer Service Forms	/	
• Horn	/		• Farebox	/	
• Driver Seat & Belt	/		• Fluids	/	
• Mirrors	/		1) Oil		
			2) Coolant		
			3) Transmission		
			4) Steering		
			5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

AW ✓

HopeSource Pre-Trip Inspection Report

Date: 12-2-11

Vehicle # 296 Operator Scott S

Mileage 196535

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment		
1) First Aid Kit	/	
2) Fire Extinguisher	/	
3) Reflections	/	
4) Strap Cutter	X	MISS
• Passenger Door Operations	✓	
• Windshield		
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	/	
• Driver Seat & Belt	/	
• Mirrors	/	

	Ok	Defect
• Radio/Cell Phone	/	
• Brakes	/	
• Parking Brake	/	
• Windshield	/	
• Headlights, Signals, 4-Ways	/	
• Tire/Wheel Condition	/	
• Lug Nut Tightness	/	
• Body Condition	/	
• Cycle W/C Lift	/	
• W/C Tiedowns & Accessories	/	
• Schedules	/	
• Customer Service Forms	/	
• Farebox	/	
• Fluids	/	
1) Oil		
2) Coolant		
3) Transmission	/	
4) Steering		
5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

AW ✓

HopeSource Pre-Trip Inspection Report

Date: 12/1/11

Vehicle # 296 Operator Bob W

Mileage 196441

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	✓		• Radio/Cell Phone		
• Interior Lights	✓		• Brakes	✓	
• Passenger Seat Condition	✓		• Parking Brake	✓	
• Emergency Equipment	✓		• Windshield		✓
1) First Aid Kit	✓		• Headlights, Signals, 4-Ways	✓	
2) Fire Extinguisher	✓		• Tire/Wheel Condition	✓	
3) Reflections	✓		• Lug Nut Tightness	✓	
4) Strap Cutter		✓	• Body Condition	✓	
• Passenger Door Operations	✓		• Cycle W/C Lift	✓	
• Windshield		✓	• W/C Tiedowns & Accessories	✓	
Wipers/Washers & Fluid	✓		• Schedules	✓	
• Fans/Defrosters	✓		• Customer Service Forms	✓	
• Horn	✓		• Farebox	✓	
• Driver Seat & Belt	✓		• Fluids	✓	
• Mirrors	✓		1) Oil	✓	
			2) Coolant	✓	
			3) Transmission	✓	
			4) Steering	✓	
			5) Brake	✓	

Mechanical Defect Report

Defect # (see above) windshield

Remarks: Rock chips

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

24 Gallons Gas

AW

HopeSource Pre-Trip Inspection Report

Date: 12-1-11

Vehicle # 296 Operator Scott S

Mileage 196353

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	✓		• Radio/Cell Phone	✓	
• Interior Lights	✓		• Brakes	✓	
• Passenger Seat Condition	✓		• Parking Brake	✓	
• Emergency Equipment	✓		• Windshield	✓	
1) First Aid Kit	✓		• Headlights, Signals, 4-Ways	✓	
2) Fire Extinguisher	✓		• Tire/Wheel Condition	✓	
3) Reflections	✓		• Lug Nut Tightness	✓	
4) Strap Cutter		✓	• Body Condition	✓	
• Passenger Door Operations	✓		• Cycle W/C Lift	✓	
• Windshield			• W/C Tiedowns & Accessories	✓	
Wipers/Washers & Fluid	✓		• Schedules	✓	
• Fans/Defrosters	✓		• Customer Service Forms	✓	
• Horn	✓		• Farebox	✓	
• Driver Seat & Belt	✓		• Fluids		
• Mirrors	✓		1) Oil		
			2) Coolant		
			3) Transmission		
			4) <u>Steering</u>		Low
			5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks: Need strap cutter,
oil a tad high

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

AW ✓

HopeSource Pre-Trip Inspection Report

Date: 11-30-11

Vehicle # 296 Operator Carry Lee

Mileage 196259

	Ok	Defect
• Fluid Leaks Under Bus	/	
• Interior Lights	/	
• Passenger Seat Condition	/	
• Emergency Equipment	/	
1) First Aid Kit	/	
2) Fire Extinguisher	/	
3) Reflections	/	
4) Strap Cutter		Missing
• Passenger Door Operations	/	
• Windshield		
Wipers/Washers & Fluid	/	
• Fans/Defrosters	/	
• Horn	/	
• Driver Seat & Belt	/	
• Mirrors	/	

	Ok	Defect
• Radio/Cell Phone	NA	
• Brakes	/	
• Parking Brake	/	
• Windshield	/	rock chips (3)
• Headlights, Signals, 4-Ways	/	
• Tire/Wheel Condition	/	
• Lug Nut Tightness	/	
• Body Condition	/	
• Cycle W/C Lift	✓	W/C Lift
• W/C Tiedowns & Accessories	✓	
• Schedules	/	
• Customer Service Forms	/	
• Farebox	/	
• Fluids	/	
1) Oil	✓	
2) Coolant	✓	
3) Transmission	✓	
4) Steering	✓	low
5) Brake	✓	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

MOTOR IS MISSING - especially in
overdrive and when a demand is put on it.

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

AW ✓

HopeSource Pre-Trip Inspection Report

Date: 11-29-11

Vehicle # 296 Operator Row William

Mileage 195,993

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	✓		• Radio/Cell Phone		
• Interior Lights	✓		• Brakes	✓	
• Passenger Seat Condition		✓	• Parking Brake	✓	
• Emergency Equipment	✓		• Windshield	✓	
1) First Aid Kit	✓		• Headlights, Signals, 4-Ways	✓	
2) Fire Extinguisher	✓		• Tire/Wheel Condition	✓	
3) Reflections	✓		• Lug Nut Tightness	✓	
4) Strap Cutter		✓	• Body Condition	✓	
• Passenger Door Operations	✓		• Cycle W/C Lift		
• Windshield		✓	• W/C Tiedowns & Accessories	✓	
Wipers/Washers & Fluid	✓		• Schedules	✓	
• Fans/Defrosters	✓		• Customer Service Forms		
• Horn	✓		• Farebox	✓	
• Driver Seat & Belt	✓		• Fluids		
• Mirrors	✓		1) Oil	✓	
			2) Coolant	✓	
			3) Transmission	✓	
			4) Steering		✓
			5) Brake	✓	

Mechanical Defect Report

Defect # (see above) Fluids #4

Remarks: power steering fluid low
small hole not bad

3 rock chips in windshield

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

35.248 Gallons Gas (no Receipt)

196,258

AW

HopeSource Pre-Trip Inspection Report

Date: 11/28/11

Vehicle # 296 Operator Scott S Mileage 195899

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition		✓
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter		✓
• Passenger Door Operations	✓	
• Windshield Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil		
2) Coolant		
3) Transmission		
4) Steering		
5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks: Small hole not bad (small)
strap cutter missing

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

AW ✓