

HopeSource Pre-Trip Inspection Report

Date: 11-28-2011

Vehicle # 295 Operator RON MACE

Mileage 196038

end 196130

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	X		• Radio/Cell Phone	X	
• Interior Lights	X		• Brakes	X	
• Passenger Seat Condition	X		• Parking Brake	X	
• Emergency Equipment	X		• Windshield	X	
1) First Aid Kit	X		• Headlights, Signals, 4-Ways	X	
2) Fire Extinguisher	X		• Tire/Wheel Condition	X	
3) Reflections	X		• Lug Nut Tightness	X	
4) Strap Cutter	X		• Body Condition	X	
• Passenger Door Operations	X		• Cycle W/C Lift	X	
• Windshield	X		• W/C Tiedowns & Accessories	X	
Wipers/Washers & Fluid	X		• Schedules	X	
• Fans/Defrosters	X		• Customer Service Forms	X	
• Horn	X		• Farebox	X	
• Driver Seat & Belt	X		• Fluids	X	
• Mirrors	X		1) Oil ✓		
			2) Coolant ✓		
			3) Transmission ✓		
			4) Steering ✓		
			5) Brake ✓		

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

AW ✓