

# HopeSource Pre-Trip Inspection Report

Vehicle # 7101

Operator Ron Pace

Mileage 44412

Date: 8-20-2012



	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

- Radio/Cell Phone
- Brakes
- Parking Brake
- Windshield
- Headlights, Signals, 4-Ways
- Tire/Wheel Condition
- Lug Nut Tightness
- Body Condition
- Cycle W/C Lift
- W/C Tiedowns & Accessories
- Schedules
- Customer Service Forms
- Farebox
- Fluids
  - 1) Oil
  - 2) Coolant
  - 3) Transmission
  - 4) Steering
  - 5) Brake

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil	✓	
2) Coolant	✓	
3) Transmission	✓	
4) Steering	✓	
5) Brake	✓	

## Mechanical Defect Report

Defect # (see above) \_\_\_\_\_

Remarks:

---



---



---

## Maintenance Disposition

Work Order # \_\_\_\_\_

Repairs Made

---



---

Date Completed \_\_\_\_\_ Repaired By: \_\_\_\_\_

Driver Reviewing Inspection: \_\_\_\_\_ Date: \_\_\_\_\_

No Fuel

AW

# HopeSource Pre-Trip Inspection Report

Date: 8-17-12

Vehicle # 7101 Operator Lee

Mileage 444325



	Ok	Defect
• Fluid Leaks Under Bus	-	
• Interior Lights	-	
• Passenger Seat Condition	-	
• Emergency Equipment	-	
1) First Aid Kit	-	
2) Fire Extinguisher	-	
3) Reflections	-	
4) Strap Cutter	-	
• Passenger Door Operations	-	
• Windshield	-	
Wipers/Washers & Fluid	-	
• Fans/Defrosters	-	
• Horn	-	
• Driver Seat & Belt	-	
• Mirrors	-	

	Ok	Defect
• Radio/Cell Phone	-	
• Brakes	-	
• Parking Brake	-	
• Windshield	-	
• Headlights, Signals, 4-Ways	-	<del>---</del>
• Tire/Wheel Condition	-	
• Lug Nut Tightness	-	
• Body Condition		X
• Cycle W/C Lift	-	
• W/C Tiedowns & Accessories	-	
• Schedules		XX
• Customer Service Forms	-	
• Farebox	-	
• Fluids	-	
1) Oil	-	XXX
2) Coolant	-	
3) Transmission	-	
4) Steering	-	
5) Brake	-	

## Mechanical Defect Report

Defect # (see above) \_\_\_\_\_

Remarks:

\* SMASHED IN ON RIGHT SIDE JUST IN FRONT OF BACK WHEEL.

\*\* NEED TRIP-INSPECTION REPORTS

Maintenance Disposition

Work Order # \_\_\_\_\_ \*\*\* Oil change sticker read 439,000 for change

Repairs Made Looks like this bus is way over due.

Right Rear tail light is out

Date Completed \_\_\_\_\_ Repaired By: \_\_\_\_\_

Driver Reviewing Inspection: \_\_\_\_\_ Date: \_\_\_\_\_


*No fuel*

*AW*

# HopeSource Pre-Trip Inspection Report

Date: 8-16-2012

Vehicle # 7101 Operator Ron Bushbaum Mileage 444,234



	Ok	Defect
• Fluid Leaks Under Bus	/	
• Interior Lights	/	
• Passenger Seat Condition	/	
• Emergency Equipment	/	
1) First Aid Kit	/	
2) Fire Extinguisher	/	
3) Reflections	/	
4) Strap Cutter	/	
• Passenger Door Operations	/	
• Windshield	/	
Wipers/Washers & Fluid	/	
• Fans/Defrosters	/	
• Horn	/	
• Driver Seat & Belt	/	
• Mirrors	/	

	Ok	Defect
• Radio/Cell Phone	/	
• Brakes	/	
• Parking Brake	/	
• Windshield	/	
• Headlights, Signals, 4-Ways	/	
• Tire/Wheel Condition	/	
• Lug Nut Tightness	/	
• Body Condition	/	
• Cycle W/C Lift	/	
• W/C Tiedowns & Accessories	/	
• Schedules	/	
• Customer Service Forms	/	
• Farebox	/	
• Fluids	/	
1) Oil	/	
2) Coolant	/	
3) Transmission	/	
4) Steering	/	
5) Brake	/	

## Mechanical Defect Report

Defect # (see above) \_\_\_\_\_

Remarks:

---



---



---

## Maintenance Disposition

Work Order # \_\_\_\_\_

Repairs Made

---



---

Date Completed \_\_\_\_\_ Repaired By: \_\_\_\_\_

Driver Reviewing Inspection: \_\_\_\_\_ Date: \_\_\_\_\_

443 324  
799



# HopeSource Pre-Trip Inspection Report

Vehicle # 7101 Operator Tom Mace

Mileage 444056

Date: 8-14-2012

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil ✓		
2) Coolant ✓		
3) Transmission ✓		
4) Steering ✓		
5) Brake ✓		

## Mechanical Defect Report

Defect # (see above) \_\_\_\_\_

Remarks:

---



---



---

## Maintenance Disposition

Work Order # \_\_\_\_\_

Repairs Made

---



---

Date Completed \_\_\_\_\_ Repaired By: \_\_\_\_\_

Driver Reviewing Inspection: \_\_\_\_\_ Date: \_\_\_\_\_

*No fuel*

*Tom Mace*

# HopeSource Pre-Trip Inspection Report

Date: 8-13-2012 ✓

Vehicle # 7101 Operator Don Wallace

Mileage 443968

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	✓		• Radio/Cell Phone	✓	
• Interior Lights	✓		• Brakes	✓	
• Passenger Seat Condition	✓		• Parking Brake	✓	
• Emergency Equipment	✓		• Windshield	✓	
1) First Aid Kit	✓		• Headlights, Signals, 4-Ways	✓	
2) Fire Extinguisher	✓		• Tire/Wheel Condition	✓	
3) Reflections	✓		• Lug Nut Tightness	✓	
4) Strap Cutter	✓		• Body Condition	✓	
• Passenger Door Operations	✓		• Cycle W/C Lift	✓	
• Windshield	✓		• W/C Tiedowns & Accessories	✓	
Wipers/Washers & Fluid	✓				
• Fans/Defrosters	✓		• Schedules	✓	
• Horn	✓		• Customer Service Forms	✓	
• Driver Seat & Belt	✓		• Farebox	✓	
• Mirrors	✓		• Fluids	✓	
			1) Oil ✓		
			2) Coolant ✓		
			3) Transmission ✓		
			4) Steering ✓		
			5) Brake ✓		

## Mechanical Defect Report

Defect # (see above) \_\_\_\_\_

Remarks: lower left mirror blew off  
last night on way home. top mirror ok

## Maintenance Disposition

Work Order # \_\_\_\_\_

Repairs Made \_\_\_\_\_

Date Completed \_\_\_\_\_ Repaired By: \_\_\_\_\_

Driver Reviewing Inspection: \_\_\_\_\_ Date: \_\_\_\_\_

MCI INSPECTION FORM ON REVERSE

*NO fuel*

*AW*

# HopeSource Pre-Trip Inspection Report

Date: 8-10-2012

Vehicle # 7101 Operator Ron Pushbaum Mileage 443817

	Ok	Defect
• Fluid Leaks Under Bus	/	
• Interior Lights	/	
• Passenger Seat Condition	/	
• Emergency Equipment	/	
1) First Aid Kit	/	
2) Fire Extinguisher	/	
3) Reflections	/	
4) Strap Cutter	/	
• Passenger Door Operations	/	
• Windshield	/	
Wipers/Washers & Fluid	/	
• Fans/Defrosters	/	
• Horn	/	
• Driver Seat & Belt	/	
• Mirrors	/	

	Ok	Defect
• Radio/Cell Phone	/	
• Brakes	/	
• Parking Brake	/	
• Windshield	/	
• Headlights, Signals, 4-Ways	/	
• Tire/Wheel Condition	/	
• Lug Nut Tightness	/	
• Body Condition	/	
• Cycle W/C Lift	/	
• W/C Tiedowns & Accessories	/	
• Schedules	/	
• Customer Service Forms	/	
• Farebox	/	
• Fluids	/	
1) Oil	/	
2) Coolant	/	
3) Transmission	/	
4) Steering	/	
5) Brake	/	

## Mechanical Defect Report

Defect # (see above) \_\_\_\_\_

Remarks:

---



---



---

## Maintenance Disposition

Work Order # \_\_\_\_\_

Repairs Made

---



---

Date Completed \_\_\_\_\_ Repaired By: \_\_\_\_\_

Driver Reviewing Inspection: \_\_\_\_\_ Date: \_\_\_\_\_

MCI INSPECTION FORM ON REVERSE