

HopeSource Pre-Trip Inspection Report

Date: 10-24-2012

Vehicle # 7105

Operator Tom Mace

Mileage 320671

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield		
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil	✓	
2) Coolant	✓	
3) Transmission		
4) Steering		
5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 10-23-2012

Vehicle # 7105 Operator Ron Bushkorn Mileage 320,402

	Ok	Defect
• Fluid Leaks Under Bus	/	
• Interior Lights	/	
• Passenger Seat Condition	/	
• Emergency Equipment	/	
1) First Aid Kit	/	
2) Fire Extinguisher	/	
3) Reflections	/	
4) Strap Cutter	/	
• Passenger Door Operations	/	
• Windshield	/	
Wipers/Washers & Fluid	/	
• Fans/Defrosters	/	
• Horn	/	
• Driver Seat & Belt	/	
• Mirrors	/	

	Ok	Defect
• Radio/Cell Phone	/	
• Brakes	/	
• Parking Brake	/	
• Windshield	/	
• Headlights, Signals, 4-Ways	/	
• Tire/Wheel Condition	/	
• Lug Nut Tightness	/	
• Body Condition	/	
• Cycle W/C Lift	/	
• W/C Tiedowns & Accessories	/	
• Schedules	/	
• Customer Service Forms	/	
• Farebox	/	
• Fluids	/	
1) Oil	/	
2) Coolant	/	
3) Transmission	/	
4) Steering	/	
5) Brake	/	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

320670

Flying J #965
2300 Canyon Rd
Ellensburg

Invoice # 80328
Date 10/23/12
Time 15:45
Auth # 325007

Pump	Gallons	Price
06	47.851	\$ 4.389

Product	Amount
ADs11	\$ 207.63

Total Sale \$ 207.63

SALE - Card Swiped

FLMAN

Acct#

#####4173

Odometer 320670

Thank You
For Choosing
Pilot Flying J

Thank you
for shopping
at Flying J!

HopeSource Pre-Trip Inspection Report

Date: 10-22-17

Vehicle # 7105 Operator Grant Thompson Mileage 320127

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	✓		• Radio/Cell Phone	✓	
• Interior Lights			• Brakes		
• Passenger Seat Condition			• Parking Brake		
• Emergency Equipment			• Windshield		
1) First Aid Kit			• Headlights, Signals, 4-Ways		
2) Fire Extinguisher			• Tire/Wheel Condition		
3) Reflections			• Lug Nut Tightness		
4) Strap Cutter			• Body Condition		
• Passenger Door Operations			• Cycle W/C Lift		
• Windshield			• W/C Tiedowns & Accessories		
Wipers/Washers & Fluid					
• Fans/Defrosters			• Schedules		
• Horn			• Customer Service Forms		
• Driver Seat & Belt			• Farebox		
• Mirrors			• Fluids		
			1) Oil		
			2) Coolant		
			3) Transmission		
			4) Steering		
			5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks: _____

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____
 Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

GRANT TR
MILEAGE: 320400
BU# 7105

Flyine J #965
2300 Canyon Rd
Ellensburg

Invoice # 80126
Date 10/22/12
Time 15:59
Auth # 176319

Pump	Gallons	Price
06	44.571	\$ 4.359

Product	Amount
ADs11	\$ 194.28

Total Sale \$ 194.28

SALE - Card Swiped

FLMAN
Acct#
#####017

Odometer 320400

Thank You
For Choosing
Pilot Flyine J

Thank you
for shopping
at Flyine J!

HopeSource Pre-Trip Inspection Report

Date: 10-19-2012

Vehicle # 7105 Operator Tom Mice Mileage 319772

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil ✓		
2) Coolant ✓		
3) Transmission ✓		
4) Steering ✓		
5) Brake ✓		

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE



BROADWAY GROUP #965
2300 Canyon Rd
Ellensburg, WA 98926

10/19/2012

SALE

Transaction #: 6286998

Qty	Name	Price	Total
1	Tractor	263.67	263.67
	Pump:	16	
	Gallons:	59.398	
	Price / Gal:	4.439	

Subtotal	263.67
Sales Tax	0.00

Total	263.67
-------	--------

Received

In House Cardless	263.67
XX1121	MANUAL
Approved	
Auth #: 375063	

Red J Barber

VehicleID	7105
DLState	
CompanyName	HOPESOURCE
InHouseAccount	550223
Odometer	
HubOdometer	8094173
TripNumber	
TrailerID	
UnitLicenseNumber	
UnitLicenseState	
TruckingCompanyName	In-House Account

www.gasvisit.com

Pos:6 Clerk:131
COPY RECEIPT

HopeSource Pre-Trip Inspection Report

Date: 10-18-2012

Vehicle # 7105 Operator Paul Hesse

Mileage 319413

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield		
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil	✓	
2) Coolant	✓	
3) Transmission	✓	
4) Steering	✓	
5) Brake	✓	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

Flying J Food
2300 Carver Rd
Tillamook

Invoice # 78987
Date 10/18/12
Time 19:14
Auth # 740642

Pump Gallons Price
05 60.078 \$ 4.439

Product Amount
ADall \$ 266.38

Total Sale \$ 266.38

SALE - Card Swiped

FLMAN
Acct #
#####4179

Odometer 319770

Thank You
For Choosing
Pilot Flying J

Thank you
for shopping
at Flying J



HopeSource Pre-Trip Inspection Report

Date: 10-17-2012

Vehicle # 7105

Operator Tom Mac

Mileage 819056

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil	✓	
2) Coolant	✓	
3) Transmission	✓	
4) Steering	✓	
5) Brake	✓	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

7105

HopeSource Pre-Trip Inspection Report

Date: 10-16-2022

Vehicle # 750T Operator Ron Bushbaum Mileage 38698

	Ok	Defect
• Fluid Leaks Under Bus	/	
• Interior Lights	/	
• Passenger Seat Condition	/	
• Emergency Equipment	/	
1) First Aid Kit	/	
2) Fire Extinguisher	/	
3) Reflections	/	
4) Strap Cutter	/	
• Passenger Door Operations	/	
• Windshield	/	
Wipers/Washers & Fluid	/	
• Fans/Defrosters	/	
• Horn	/	
• Driver Seat & Belt	/	
• Mirrors	/	

add 1 gal antifreeze

	Ok	Defect
• Radio/Cell Phone	/	
• Brakes	/	
• Parking Brake	/	
• Windshield	/	
• Headlights, Signals, 4-Ways	/	X
• Tire/Wheel Condition	/	
• Lug Nut Tightness	/	
• Body Condition	/	
• Cycle W/C Lift	/	
• W/C Tiedowns & Accessories	/	
• Schedules	/	
• Customer Service Forms	/	
• Farebox	/	
• Fluids	/	
1) Oil	/	
2) Coolant	/	
3) Transmission	/	
4) Steering	/	
5) Brake	/	

Mechanical Defect Report

Defect # (see above)

Remarks: Left Rear inside tail light

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

[Handwritten signature]

HopeSource Pre-Trip Inspection Report

Date: 10-15-12

Vehicle # 7105 Operator Grant Thompson Mileage 383310

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil	✓	
2) Coolant	✓	
3) Transmission	✓	
4) Steering	✓	
5) Brake	✓	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 10-12-2012

Vehicle # 7105 Operator Tom Wace Mileage 317981

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil	✓	
2) Coolant	✓	
3) Transmission	✓	
4) Steering	✓	
5) Brake	✓	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 10-11-2012

Vehicle # 7105 Operator Donna

Mileage 317624

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil ✓		
2) Coolant ✓		
3) Transmission ✓		
4) Steering ✓		
5) Brake ✓		

Mechanical Defect Report

Defect # (see above) _____
 Remarks: Need to clean seat and wheelchair tracks and lube RJB

Maintenance Disposition

Work Order # _____
 Repairs Made _____

Date Completed _____ Repaired By: _____
 Driver Reviewing Inspection: _____ Date: _____

[Handwritten signature]

HopeSource Pre-Trip Inspection Report

Date: 10-10-2012

Vehicle # 7105 Operator Tom Maco

Mileage 317267

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil	✓	
2) Coolant	✓	
3) Transmission	✓	
4) Steering	✓	
5) Brake	✓	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

317624
59.6

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 10-9-2012

Vehicle # 7105 Operator Ron Bushman Mileage 316,995

	Ok	Defect
• Fluid Leaks Under Bus	/	
• Interior Lights	/	
• Passenger Seat Condition	/	
• Emergency Equipment	/	
1) First Aid Kit	/	
2) Fire Extinguisher	/	
3) Reflections	/	
4) Strap Cutter	/	
• Passenger Door Operations	/	
• Windshield	/	
Wipers/Washers & Fluid	/	
• Fans/Defrosters	/	
• Horn	/	
• Driver Seat & Belt	/	
• Mirrors	/	

	Ok	Defect
• Radio/Cell Phone	/	
• Brakes	/	
• Parking Brake	/	
• Windshield	/	
• Headlights, Signals, 4-Ways	/	
• Tire/Wheel Condition	/	
• Lug Nut Tightness	/	
• Body Condition	/	
• Cycle W/C Lift	/	
• W/C Tiedowns & Accessories	/	
• Schedules	/	
• Customer Service Forms	/	
• Farebox	/	
• Fluids	/	
1) Oil	/	
2) Coolant	/	
3) Transmission	/	
4) Steering	/	
5) Brake	/	

317,267
46 gal.

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 10-5-2017

Vehicle # 7105 Operator Rou Mace

Mileage 314637

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	<input checked="" type="checkbox"/>	<input type="checkbox"/>	• Radio/Cell Phone	<input checked="" type="checkbox"/>	<input type="checkbox"/>
• Interior Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	• Brakes	<input checked="" type="checkbox"/>	<input type="checkbox"/>
• Passenger Seat Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	• Parking Brake	<input checked="" type="checkbox"/>	<input type="checkbox"/>
• Emergency Equipment	<input checked="" type="checkbox"/>	<input type="checkbox"/>	• Windshield	<input checked="" type="checkbox"/>	<input type="checkbox"/>
1) First Aid Kit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	• Headlights, Signals, 4-Ways	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2) Fire Extinguisher	<input checked="" type="checkbox"/>	<input type="checkbox"/>	• Tire/Wheel Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3) Reflections	<input checked="" type="checkbox"/>	<input type="checkbox"/>	• Lug Nut Tightness	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4) Strap Cutter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	• Body Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>
• Passenger Door Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	• Cycle W/C Lift	<input checked="" type="checkbox"/>	<input type="checkbox"/>
• Windshield	<input type="checkbox"/>	<input type="checkbox"/>	• W/C Tiedowns & Accessories	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Wipers/Washers & Fluid	<input checked="" type="checkbox"/>	<input type="checkbox"/>	• Schedules	<input checked="" type="checkbox"/>	<input type="checkbox"/>
• Fans/Defrosters	<input checked="" type="checkbox"/>	<input type="checkbox"/>	• Customer Service Forms	<input checked="" type="checkbox"/>	<input type="checkbox"/>
• Horn	<input checked="" type="checkbox"/>	<input type="checkbox"/>	• Farebox	<input checked="" type="checkbox"/>	<input type="checkbox"/>
• Driver Seat & Belt	<input checked="" type="checkbox"/>	<input type="checkbox"/>	• Fluids	<input checked="" type="checkbox"/>	<input type="checkbox"/>
• Mirrors	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1) Oil	<input checked="" type="checkbox"/>	<input type="checkbox"/>
			2) Coolant		
			3) Transmission		
			4) Steering		
			5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks: _____

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

AW

HopeSource Pre-Trip Inspection Report

Date: 10-4-2012

Vehicle # 7105 Operator Tom Mace Mileage 316281

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil		
2) Coolant		
3) Transmission		
4) Steering		
5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks: _____

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

HopeSource Pre-Trip Inspection Report

Date: 10-3-2012

Vehicle # 7105 Operator Karl Wace Mileage 316096

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield		
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil		
2) Coolant	✓	
3) Transmission		
4) Steering		
5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks:

top back & middle clearance lights are out

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

AW ✓

HopeSource Pre-Trip Inspection Report

Date: 10-2-2012

Vehicle # 7105 Operator Ron Bushbaum Mileage 315,736

	Ok	Defect
• Fluid Leaks Under Bus	/	
• Interior Lights	/	
• Passenger Seat Condition	/	
• Emergency Equipment	/	
1) First Aid Kit	/	
2) Fire Extinguisher	/	
3) Reflections	/	
4) Strap Cutter	/	
• Passenger Door Operations	/	
• Windshield	/	
Wipers/Washers & Fluid	/	
• Fans/Defrosters	/	
• Horn	/	
• Driver Seat & Belt	/	
• Mirrors	/	

	Ok	Defect
• Radio/Cell Phone	/	
• Brakes	/	
• Parking Brake	/	
• Windshield	/	
• Headlights, Signals, 4-Ways	/	/
• Tire/Wheel Condition	/	
• Lug Nut Tightness	/	
• Body Condition	/	
• Cycle W/C Lift	/	
• W/C Tiedowns & Accessories	/	
• Schedules	/	
• Customer Service Forms	/	
• Farebox	/	
• Fluids	/	
1) Oil	/	
2) Coolant	/	
3) Transmission	/	
4) Steering	/	
5) Brake	/	

Mechanical Defect Report

Defect # (see above) _____

Remarks: L Rear Tail Light Not Working

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 9-28-12

Vehicle # 5105 Operator Pomilio Romo Mileage 315,105

	Ok	Defect
• Fluid Leaks Under Bus	/	
• Interior Lights	/	
• Passenger Seat Condition	/	
• Emergency Equipment	/	
1) First Aid Kit	/	
2) Fire Extinguisher	/	
3) Reflections	/	
4) Strap Cutter	/	
• Passenger Door Operations	/	
• Windshield	/	
Wipers/Washers & Fluid	/	
• Fans/Defrosters	/	
• Horn	/	
• Driver Seat & Belt	/	
• Mirrors	/	

	Ok	Defect
• Radio/Cell Phone	/	
• Brakes	/	
• Parking Brake	/	
• Windshield	/	
• Headlights, Signals, 4-Ways	/	
• Tire/Wheel Condition	/	
• Lug Nut Tightness	/	
• Body Condition	/	
• Cycle W/C Lift	/	
• W/C Tiedowns & Accessories	/	
• Schedules	/	
• Customer Service Forms	/	
• Farebox	/	
• Fluids	/	
1) Oil	/	
2) Coolant	/	
3) Transmission	/	
4) Steering	/	
5) Brake	/	

315,109

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 9-21-2012

Vehicle # 7105 Operator Ron Bushbaum Mileage 315,009

	Ok	Defect
• Fluid Leaks Under Bus	/	
• Interior Lights	/	
• Passenger Seat Condition	/	
• Emergency Equipment	/	
1) First Aid Kit	/	
2) Fire Extinguisher	/	
3) Reflections	/	
4) Strap Cutter	/	
• Passenger Door Operations	/	
• Windshield	/	
Wipers/Washers & Fluid	/	
• Fans/Defrosters	/	
• Horn	/	
• Driver Seat & Belt	/	
• Mirrors	/	

	Ok	Defect
• Radio/Cell Phone	/	
• Brakes	/	
• Parking Brake	/	
• Windshield	/	
• Headlights, Signals, 4-Ways	/	
• Tire/Wheel Condition	/	
• Lug Nut Tightness	/	
• Body Condition	/	
• Cycle W/C Lift	/	
• W/C Tiedowns & Accessories	/	
• Schedules	/	
• Customer Service Forms	/	
• Farebox	/	
• Fluids	/	
1) Oil	/	
2) Coolant	/	
3) Transmission	/	
4) Steering	/	
5) Brake	/	

Mechanical Defect Report

Defect # (see above) _____

Remarks: _____

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____
 Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 9-18-2012

Vehicle # 7105 Operator Ron Bushbar Mileage 314,559

	Ok	Defect
• Fluid Leaks Under Bus	/	
• Interior Lights	/	
• Passenger Seat Condition	/	
• Emergency Equipment	/	
1) First Aid Kit	/	
2) Fire Extinguisher	/	
3) Reflections	/	
4) Strap Cutter	/	
• Passenger Door Operations	/	
• Windshield	/	
Wipers/Washers & Fluid	/	
• Fans/Defrosters	/	
• Horn	/	
• Driver Seat & Belt	/	
• Mirrors	/	

	Ok	Defect
• Radio/Cell Phone	/	
• Brakes	/	
• Parking Brake	/	
• Windshield	/	
• Headlights, Signals, 4-Ways	/	
• Tire/Wheel Condition	/	
• Lug Nut Tightness	/	
• Body Condition	/	
• Cycle W/C Lift	/	
• W/C Tiedowns & Accessories	/	
• Schedules	/	
• Customer Service Forms	/	
• Farebox	/	
• Fluids	/	
1) Oil	/	
2) Coolant	/	
3) Transmission	/	
4) Steering	/	
5) Brake	/	

Trans dip stick broke

Mechanical Defect Report

Defect # (see above) _____

Remarks: ordered thru NAPA!

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

HopeSource Pre-Trip Inspection Report

Date: 9-17-12

Vehicle # 7105 Operator Grans Thompson Mileage 314287

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights		
• Passenger Seat Condition		
• Emergency Equipment		
1) First Aid Kit		
2) Fire Extinguisher		
3) Reflections		
4) Strap Cutter		
• Passenger Door Operations		
• Windshield		
Wipers/Washers & Fluid		
• Fans/Defrosters		
• Horn		
• Driver Seat & Belt		
• Mirrors		

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes		
• Parking Brake		
• Windshield		
• Headlights, Signals, 4-Ways		
• Tire/Wheel Condition		
• Lug Nut Tightness		
• Body Condition		
• Cycle W/C Lift		
• W/C Tiedowns & Accessories		
• Schedules		
• Customer Service Forms		
• Farebox		
• Fluids		
1) Oil		
2) Coolant		
3) Transmission		
4) Steering		
5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks: _____

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____
 Driver Reviewing Inspection: _____ Date: _____

314,558
 44%

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 9-12-2012

Vehicle # 7105 Operator Roullace Mileage 313575

SEAN THOMPSON

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil	✓	
2) Coolant	✓	
3) Transmission	✓	
4) Steering	✓	
5) Brake	✓	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

[Handwritten signature]

7105

HopeSource Pre-Trip Inspection Report

Date: 9-11-2012

Vehicle # 7501 Operator Don Busham Mileage 313,219

	Ok	Defect
• Fluid Leaks Under Bus	/	
• Interior Lights	/	
• Passenger Seat Condition	/	
• Emergency Equipment	/	
1) First Aid Kit	/	
2) Fire Extinguisher	/	
3) Reflections	/	
4) Strap Cutter	/	
• Passenger Door Operations	/	
• Windshield	/	
Wipers/Washers & Fluid	/	
• Fans/Defrosters	/	
• Horn	/	
• Driver Seat & Belt	/	
• Mirrors	/	

	Ok	Defect
• Radio/Cell Phone	/	
• Brakes	/	
• Parking Brake	/	
• Windshield	/	
• Headlights, Signals, 4-Ways	/	
• Tire/Wheel Condition	/	
• Lug Nut Tightness	/	
• Body Condition	/	
• Cycle W/C Lift	/	
• W/C Tiedowns & Accessories	/	
• Schedules	/	
• Customer Service Forms	/	
• Farebox	/	
• Fluids	/	
1) Oil	/	
2) Coolant	/	
3) Transmission	/	
4) Steering	/	
5) Brake	/	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

AWW

HopeSource Pre-Trip Inspection Report

Date: 8-31-12

Vehicle # 714 Operator Suttis
 (7105) New #

Mileage 312709

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	NONE	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil	✓	
2) Coolant	✓	
3) Transmission	✓	
4) Steering	✓	
5) Brake	✓	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

Handwritten signature/initials

HopeSource Pre-Trip Inspection Report

Date: 8/28/12

Vehicle # 714 Operator Scott S Mileage 312610

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	

- 1) Oil ✓
- 2) Coolant ✓
- 3) Transmission ✓
- 4) Steering ✓
- 5) Brake ✓

312707
17' ✓

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 8-27-12

Vehicle # 214 Operator B. Williams Mileage 312815

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone		✓
• Brakes	✓	
• Parking Brake	✓	
• Windshield		✓
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil		
2) Coolant		
3) Transmission		
4) Steering		
5) Brake		

312609
51.2 ✓

Mechanical Defect Report

Defect # (see above)

Remarks: NO Radio, Rock chips windshield
Back of seat 31 Big RP.

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____
Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 8-24-12

Vehicle # 714 Operator Lee

Mileage 312420

	Ok	Defect
• Fluid Leaks Under Bus	/	
• Interior Lights	/	
• Passenger Seat Condition	/	
• Emergency Equipment	/	
1) First Aid Kit	/	
2) Fire Extinguisher	/	
3) Reflections	/	
4) Strap Cutter	/	
• Passenger Door Operations	/	
• Windshield Wipers/Washers & Fluid	/	
• Fans/Defrosters	/	
• Horn	/	
• Driver Seat & Belt	/	
• Mirrors	/	

	Ok	Defect
• Radio/Cell Phone	NA	
• Brakes	/	
• Parking Brake	/	
• Windshield	/	
• Headlights, Signals, 4-Ways	/	
• Tire/Wheel Condition	/	
• Lug Nut Tightness	/	
• Body Condition	/	
• Cycle W/C Lift	/	
• W/C Tiedowns & Accessories	/	
• Schedules	/	
• Customer Service Forms	/	
• Farebox	/	
• Fluids	/	
1) Oil	/	
2) Coolant	/	
3) Transmission	/	
4) Steering	/	
5) Brake	/	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

HopeSource Pre-Trip Inspection Report

Date: 8-28-72

Vehicle # 714 Operator Rehman Mileage 312325

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	✓		• Radio/Cell Phone		✓
• Interior Lights	✓		• Brakes	✓	
• Passenger Seat Condition	✓		• Parking Brake	✓	
• Emergency Equipment	✓		• Windshield		✓
1) First Aid Kit	✓		• Headlights, Signals, 4-Ways	✓	
2) Fire Extinguisher	✓		• Tire/Wheel Condition	✓	
3) Reflections	✓		• Lug Nut Tightness	✓	
4) Strap Cutter	✓		• Body Condition	✓	
• Passenger Door Operations	✓		• Cycle W/C Lift	✓	
• Windshield	✓		• W/C Tiedowns & Accessories	✓	
Wipers/Washers & Fluid	✓		• Schedules	✓	
• Fans/Defrosters	✓		• Customer Service Forms	✓	
• Horn	✓		• Farebox	✓	
• Driver Seat & Belt	✓		• Fluids	✓	
• Mirrors	✓		1) Oil		
			2) Coolant	✓	
			3) Transmission		
			4) Steering		
			5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks: No Radio, Rock chips windshields

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 8-22-12

Vehicle # 719 Operator Lee

Mileage 312230

	Ok	Defect
• Fluid Leaks Under Bus	—	
• Interior Lights	—	
• Passenger Seat Condition	—	
• Emergency Equipment	—	
1) First Aid Kit	—	
2) Fire Extinguisher	—	
3) Reflections	—	
4) Strap Cutter	—	
• Passenger Door Operations	—	
• Windshield	—	
Wipers/Washers & Fluid	—	
• Fans/Defrosters	—	
• Horn	—	
• Driver Seat & Belt	—	
• Mirrors	—	

	Ok	Defect
• Radio/Cell Phone	NA	
• Brakes	—	
• Parking Brake	—	
• Windshield	—	
• Headlights, Signals, 4-Ways	—	
• Tire/Wheel Condition	—	
• Lug Nut Tightness	—	
• Body Condition	—	
• Cycle W/C Lift	—	
• W/C Tiedowns & Accessories	—	
• Schedules	—	
• Customer Service Forms	—	
• Farebox	—	
• Fluids	—	
1) Oil	—	
2) Coolant	—	
3) Transmission	—	
4) Steering	—	
5) Brake	—	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 8-21-12

Vehicle # 714 Operator Scott S Mileage 312132

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil ✓		
2) Coolant ✓		
3) Transmission ✓		
4) Steering ✓		
5) Brake ✓		

Mechanical Defect Report

Defect # (see above) _____

Remarks: Swept out Bus

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 8-13-12

Vehicle # 714 Operator Ron W Mileage 311291

By Scott S

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	✓		• Radio/Cell Phone	NONE	
• Interior Lights	✓		• Brakes	✓	
• Passenger Seat Condition	✓		• Parking Brake	✓	
• Emergency Equipment	✓		• Windshield	✓	
1) First Aid Kit	✓		• Headlights, Signals, 4-Ways	✓	
2) Fire Extinguisher	✓		• Tire/Wheel Condition	✓	
3) Reflections	✓		• Lug Nut Tightness	✓	
4) Strap Cutter	✓		• Body Condition	✓	
• Passenger Door Operations	✓		• Cycle W/C Lift	✓	
• Windshield	✓		• W/C Tiedowns & Accessories	✓	
Wipers/Washers & Fluid	✓				
• Fans/Defrosters	✓		• Schedules	✓	
• Horn	✓		• Customer Service Forms	✓	
• Driver Seat & Belt	✓		• Farebox	✓	
• Mirrors	✓		• Fluids	✓	
			1) Oil -		
			2) Coolant -		
			3) Transmission -		
			4) Steering -		
			5) Brake -		

Mechanical Defect Report

Defect # (see above) _____

Remarks: _____

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

311473
31.2

✓

[Handwritten Signature]

HopeSource Pre-Trip Inspection Report

Date: 8-10-12

Vehicle # 714 Operator R. Williams Mileage 31110

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	✓		• Radio/Cell Phone		✓
• Interior Lights	✓		• Brakes	✓	
• Passenger Seat Condition	✓		• Parking Brake	✓	
• Emergency Equipment	✓		• Windshield		✓
1) First Aid Kit	✓		• Headlights, Signals, 4-Ways	✓	
2) Fire Extinguisher	✓		• Tire/Wheel Condition	✓	
3) Reflections	✓		• Lug Nut Tightness	✓	
4) Strap Cutter	✓		• Body Condition	✓	
• Passenger Door Operations	✓		• Cycle W/C Lift	✓	
• Windshield			• W/C Tiedowns & Accessories	✓	
Wipers/Washers & Fluid	✓		• Schedules	✓	
• Fans/Defrosters	✓		• Customer Service Forms	✓	
• Horn	✓		• Farebox	✓	
• Driver Seat & Belt	✓		• Fluids	✓	
• Mirrors	✓		1) Oil		
			2) Coolant		
			3) Transmission		
			4) Steering		
			5) Brake		

Mechanical Defect Report

Defect # (see above)

Remarks: no Radio, Rock chips windshields

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

311290
32.7 ✓
AW ✓

HopeSource Pre-Trip Inspection Report

Date: 8-14-12

Vehicle # 714 Operator Ron W Mileage 311474

By Scot S

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	✓		• Radio/Cell Phone	✓	
• Interior Lights	✓		• Brakes	✓	
• Passenger Seat Condition	✓		• Parking Brake	✓	
• Emergency Equipment	✓		• Windshield	✓	
1) First Aid Kit	✓		• Headlights, Signals, 4-Ways	✓	X
2) Fire Extinguisher	✓		• Tire/Wheel Condition	✓	
3) Reflections	✓		• Lug Nut Tightness	✓	
4) Strap Cutter	✓		• Body Condition	✓	
• Passenger Door Operations	✓		• Cycle W/C Lift	✓	
• Windshield	✓		• W/C Tiedowns & Accessories	✓	
Wipers/Washers & Fluid	✓				
• Fans/Defrosters	✓		• Schedules	✓	
• Horn	✓		• Customer Service Forms	✓	
• Driver Seat & Belt	✓		• Farebox	✓	
• Mirrors	✓		• Fluids	✓	
			1) Oil ✓		
			2) Coolant ✓		
			3) Transmission ✓		
			4) Steering ✓		
			5) Brake ✓		

Mechanical Defect Report

Defect # (see above) _____

Remarks: Driver side tail light out
will inform Yakima Transit

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

311658
35-05 ✓

[Handwritten signature]

HopeSource Pre-Trip Inspection Report

Date: 8-15-12

Vehicle # 714 Operator Lee

Mileage 311668

	Ok	Defect
• Fluid Leaks Under Bus	-	
• Interior Lights	-	
• Passenger Seat Condition	-	
• Emergency Equipment	-	
1) First Aid Kit	-	
2) Fire Extinguisher	-	
3) Reflections	-	
4) Strap Cutter	-	
• Passenger Door Operations	-	
• Windshield	-	
Wipers/Washers & Fluid	-	
• Fans/Defrosters	-	
• Horn	-	
• Driver Seat & Belt	-	
• Mirrors	-	

	Ok	Defect
• Radio/Cell Phone	NA	
• Brakes	-	
• Parking Brake	-	
• Windshield	-	
• Headlights, Signals, 4-Ways	-	
• Tire/Wheel Condition	-	
• Lug Nut Tightness	-	
• Body Condition	-	
• Cycle W/C Lift	-	
• W/C Tiedowns & Accessories	-	
• Schedules	-	
• Customer Service Forms	-	
• Farebox	-	
• Fluids	-	
1) Oil	-	
2) Coolant	-	
3) Transmission	-	
4) Steering	-	
5) Brake	-	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

No fuel ✓

[Handwritten signature]

HopeSource Pre-Trip Inspection Report

Date: 8-16-12

Vehicle # 714 Operator B. Whitman Mileage 311763

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid		
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone		✓
• Brakes	✓	
• Parking Brake	✓	
• Windshield		✓
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil		
2) Coolant	✓	
3) Transmission		
4) Steering		
5) Brake		

Mechanical Defect Report

Defect # (see above) _____
 Remarks: No Radio, Rock chips windshields

Maintenance Disposition

Work Order # _____
 Repairs Made _____

Date Completed _____ Repaired By: _____
 Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

*311856
40. ✓*

HopeSource Pre-Trip Inspection Report

Date: 8-17-12

Vehicle # 714

Operator B. Williams

Mileage 311 896

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	✓		• Radio/Cell Phone		✓
• Interior Lights	✓		• Brakes	✓	
• Passenger Seat Condition	✓		• Parking Brake	✓	
• Emergency Equipment	✓		• Windshield		✓
1) First Aid Kit	✓		• Headlights, Signals, 4-Ways	✓	
2) Fire Extinguisher	✓		• Tire/Wheel Condition	✓	
3) Reflections	✓		• Lug Nut Tightness	✓	
4) Strap Cutter	✓		• Body Condition	✓	
• Passenger Door Operations	✓		• Cycle W/C Lift	✓	
• Windshield			• W/C Tiedowns & Accessories	✓	
Wipers/Washers & Fluid	✓		• Schedules	✓	
• Fans/Defrosters	✓		• Customer Service Forms	✓	
• Horn	✓		• Farebox	✓	
• Driver Seat & Belt	✓		• Fluids	✓	
• Mirrors	✓		1) Oil		
			2) Coolant	—	
			3) Transmission		
			4) Steering		
			5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks: NO Radio, Rock Chips windshields

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

3/2035
3301
✓