

HopeSource Pre-Trip Inspection Report

Date: 11-7-12

Vehicle # 7106

Operator Scott S

Mileage 280847

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid		
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids		
1) Oil ✓		
2) Coolant ✓		
3) Transmission ✓		
4) Steering ✓		
5) Brake		

7106
281211
56.4 gal.

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 12-5-12

Vehicle # 7106 Operator Scott S Mileage 280118

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	✓		• Radio/Cell Phone	✓	
• Interior Lights	✓		• Brakes	✓	
• Passenger Seat Condition	✓		• Parking Brake	✓	
• Emergency Equipment	✓		• Windshield	✓	
1) First Aid Kit	✓		• Headlights, Signals, 4-Ways	✓	
2) Fire Extinguisher	✓		• Tire/Wheel Condition	✓	
3) Reflections	✓		• Lug Nut Tightness	✓	
4) Strap Cutter	✓		• Body Condition	✓	
• Passenger Door Operations	✓		• Cycle W/C Lift	✓	
• Windshield	✓		• W/C Tiedowns & Accessories	✓	
Wipers/Washers & Fluid	✓				
• Fans/Defrosters	✓		• Schedules	✓	
• Horn	✓		• Customer Service Forms	✓	
• Driver Seat & Belt	✓		• Farebox	✓	
• Mirrors	✓		• Fluids	✓	
			1) Oil	✓	
			2) Coolant	✓	
			3) Transmission	✓	
			4) Steering	✓	
			5) Brake	✓	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

AW

HopeSource Pre-Trip Inspection Report

Date: 11-28-12

Vehicle # 7106 Operator B Whitman Mileage 279657

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	✓		• Radio/Cell Phone	✓	
• Interior Lights	✓		• Brakes	✓	
• Passenger Seat Condition	✓		• Parking Brake	✓	
• Emergency Equipment	✓		• Windshield	✓	✓
1) First Aid Kit	✓		• Headlights, Signals, 4-Ways	✓	
2) Fire Extinguisher	✓		• Tire/Wheel Condition	✓	
3) Reflections	✓		• Lug Nut Tightness	✓	
4) Strap Cutter	✓		• Body Condition	✓	
• Passenger Door Operations	✓		• Cycle W/C Lift	✓	
• Windshield	✓		• W/C Tiedowns & Accessories	✓	
Wipers/Washers & Fluid	✓				
• Fans/Defrosters	✓		• Schedules	✓	
• Horn	✓		• Customer Service Forms	✓	
• Driver Seat & Belt	✓		• Farebox	✓	
• Mirrors	✓		• Fluids	✓	
			1) Oil		
			2) Coolant		
			3) Transmission	✓	
			4) Steering		
			5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks: Rock chips

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

HopeSource Pre-Trip Inspection Report

Date: 11-27-12

Vehicle # 7106 Operator Scott S

Mileage 279561

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil		
2) Coolant	low	
3) Transmission	will	Fill
4) Steering		
5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____
 Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 11-21-12

Vehicle # 7106 Operator Scott S Mileage 229193

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield		
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil -		
2) Coolant ✓		
3) Transmission ✓		
4) Steering ✓		
5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 11-20-12

Vehicle # 7106 Operator Scott S Mileage 279093

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	✓		• Radio/Cell Phone	✓	
• Interior Lights	✓		• Brakes	✓	
• Passenger Seat Condition	✓		• Parking Brake	✓	
• Emergency Equipment	✓		• Windshield	✓	
1) First Aid Kit	✓		• Headlights, Signals, 4-Ways	✓	
2) Fire Extinguisher	✓		• Tire/Wheel Condition	✓	
3) Reflections	✓		• Lug Nut Tightness	✓	
4) Strap Cutter	✓		• Body Condition	✓	
• Passenger Door Operations	✓		• Cycle W/C Lift	✓	
• Windshield	✓		• W/C Tiedowns & Accessories	✓	
Wipers/Washers & Fluid	✓				
• Fans/Defrosters	✓		• Schedules	✓	
• Horn	✓		• Customer Service Forms	✓	
• Driver Seat & Belt	✓		• Farebox	✓	
• Mirrors	✓		• Fluids	✓	
			1) Oil -		
			2) Coolant +		X
			3) Transmission -		
			4) Steering -		
			5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks: Coolant Low going to fill.

I think I found leak will perform yakima T.

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

ASV

HopeSource Pre-Trip Inspection Report

Date: 11-19-12

Vehicle # 7106 Operator Leo

Mileage 278811

	Ok	Defect
• Fluid Leaks Under Bus	/	
• Interior Lights	/	
• Passenger Seat Condition	/	
• Emergency Equipment	/	
1) First Aid Kit	/	
2) Fire Extinguisher	/	
3) Reflections	/	
4) Strap Cutter	/	
• Passenger Door Operations	/	
• Windshield		
Wipers/Washers & Fluid	/	**
• Fans/Defrosters	/	
• Horn	/	
• Driver Seat & Belt	/	
• Mirrors	/	

	Ok	Defect
• Radio/Cell Phone	-	
• Brakes	-	
• Parking Brake	-	
• Windshield	-	
• Headlights, Signals, 4-Ways	-	*
• Tire/Wheel Condition	-	
• Lug Nut Tightness	/	
• Body Condition	-	
• Cycle W/C Lift	-	
• W/C Tiedowns & Accessories	-	
• Schedules	-	
• Customer Service Forms	-	
• Farebox	-	
• Fluids		
1) Oil	-	
2) Coolant	-	
3) Transmission	-	
4) Steering	-	
5) Brake	-	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

~~* BACK LEFT TAIL LIGHT LENS IS CRACKED~~
~~** Left wiper washer is not working~~
 Right wiper is not working

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

Leo

HopeSource Pre-Trip Inspection Report

Date: 11-16-12

Vehicle # 2106

Operator B. Whitman

Mileage 278716

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield		✓
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil		
2) Coolant		
3) Transmission	✓	
4) Steering		
5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks: Rock chips

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____

Repaired By: _____

Driver Reviewing Inspection: _____

Date: _____

MCI INSPECTION FORM ON REVERSE

AW

HopeSource Pre-Trip Inspection Report

Date: 11-14-12

Vehicle # 7106 Operator Lee

Mileage 278340

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil	✓	
2) Coolant	✓	
3) Transmission	✓	
4) Steering	✓	
5) Brake	✓	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 11-13-12

Vehicle # 7106 Operator B Whitman Mileage 278063

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield		✓
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil		
2) Coolant		
3) Transmission		
4) Steering		
5) Brake		

Mechanical Defect Report

Defect # (see above)

Remarks: Rock chips

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____

Repaired By: _____

Driver Reviewing Inspection: _____

Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 11-9-12

Vehicle # 7106

Operator Paul Amari

Mileage 277965

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	✓
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil		
2) Coolant		
3) Transmission	✓	
4) Steering		
5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks: Rock chips

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____

Repaired By: _____

Driver Reviewing Inspection: _____

Date: _____

MCI INSPECTION FORM ON REVERSE

Handwritten signature

HopeSource Pre-Trip Inspection Report

Date: 11-7-12

Vehicle # 7106 Operator Scott S Mileage 277412

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	✓		• Radio/Cell Phone	✓	
• Interior Lights	✓		• Brakes	✓	
• Passenger Seat Condition	✓		• Parking Brake	✓	
• Emergency Equipment	✓		• Windshield	✓	
1) First Aid Kit	✓		• Headlights, Signals, 4-Ways	✓	
2) Fire Extinguisher	✓		• Tire/Wheel Condition	✓	
3) Reflections	✓		• Lug Nut Tightness	✓	
4) Strap Cutter	✓		• Body Condition	✓	
• Passenger Door Operations	✓		• Cycle W/C Lift	✓	
• Windshield			• W/C Tiedowns & Accessories	✓	
Wipers/Washers & Fluid	✓				
• Fans/Defrosters	✓		• Schedules	✓	
• Horn	✓		• Customer Service Forms	✓	
• Driver Seat & Belt	✓		• Farebox	✓	
• Mirrors	✓		• Fluids	✓	
			1) Oil ✓		
			2) Coolant ✓		
			3) Transmission ✓		
			4) Steering ✓		
			5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks: Spent 1 HR with shop vac
cleaning inside of bus (Floor + seats)

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 11-5-12

Vehicle # 7106 Operator Scott S Mileage 277316

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield		
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil	✓	
2) Coolant	✓	
3) Transmission	✓	
4) Steering	✓	
5) Brake	✓	

277410
23.0

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 10-25-12

Vehicle # 7106 Operator Scott S

Mileage 277042

	Ok	Defect
• Fluid Leaks Under Bus	X	
• Interior Lights	X	
• Passenger Seat Condition	X	
• Emergency Equipment	X	
1) First Aid Kit	X	
2) Fire Extinguisher	X	
3) Reflections	X	
4) Strap Cutter	X	
• Passenger Door Operations	X	
• Windshield	X	
Wipers/Washers & Fluid	X	
• Fans/Defrosters	X	
• Horn	X	
• Driver Seat & Belt	X	
• Mirrors	X	

	Ok	Defect
• Radio/Cell Phone	X	
• Brakes	X	
• Parking Brake	X	
• Windshield	X	
• Headlights, Signals, 4-Ways	X	
• Tire/Wheel Condition	X	
• Lug Nut Tightness	X	
• Body Condition	X	
• Cycle W/C Lift	X	
• W/C Tiedowns & Accessories	X	
• Schedules	X	
• Customer Service Forms	X	
• Farebox	X	
• Fluids	X	
1) Oil ✓		
2) Coolant ✓		
3) Transmission ✓		
4) Steering ✓		
5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks: _____

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 10-23-11

Vehicle # 7106 Operator R. Whitman Mileage 276766

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	✓		• Radio/Cell Phone	✓	
• Interior Lights	✓		• Brakes	✓	
• Passenger Seat Condition	✓		• Parking Brake	✓	
• Emergency Equipment	✓		• Windshield	✓	
1) First Aid Kit	✓		• Headlights, Signals, 4-Ways	✓	
2) Fire Extinguisher	✓		• Tire/Wheel Condition	✓	
3) Reflections	✓		• Lug Nut Tightness	✓	
4) Strap Cutter	✓		• Body Condition	✓	
• Passenger Door Operations	✓		• Cycle W/C Lift	✓	
• Windshield	✓		• W/C Tiedowns & Accessories	✓	
Wipers/Washers & Fluid	✓				
• Fans/Defrosters	✓		• Schedules	✓	
• Horn	✓		• Customer Service Forms	✓	
• Driver Seat & Belt	✓		• Farebox	✓	
• Mirrors	✓		• Fluids	✓	
			1) Oil		
			2) Coolant	✓	
			3) Transmission		
			4) Steering		
			5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 10-22-12

Vehicle # 2106 Operator Lee

Mileage 276487

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil	✓	
2) Coolant	*	
3) Transmission	✓	
4) Steering	✓	
5) Brake	✓	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

* Low

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

AW

HopeSource Pre-Trip Inspection Report

Date: 10-19-12

Vehicle # 7106

Operator Scott S

Mileage 276210

	Ok	Defect
• Fluid Leaks Under Bus	X	
• Interior Lights	X	
• Passenger Seat Condition	X	
• Emergency Equipment	X	
1) First Aid Kit	X	
2) Fire Extinguisher	X	
3) Reflections	X	
4) Strap Cutter	X	
• Passenger Door Operations	X	
• Windshield Wipers/Washers & Fluid	X	
• Fans/Defrosters	X	
• Horn	X	
• Driver Seat & Belt	X	
• Mirrors	X	

	Ok	Defect
• Radio/Cell Phone	X	
• Brakes	X	
• Parking Brake	X	
• Windshield	X	
• Headlights, Signals, 4-Ways	X	
• Tire/Wheel Condition	X	
• Lug Nut Tightness	X	
• Body Condition	X	
• Cycle W/C Lift	X	
• W/C Tiedowns & Accessories	X	
• Schedules	X	
• Customer Service Forms	X	
• Farebox	X	
• Fluids	X	
1) Oil ✓		
2) Coolant ✓		
3) Transmission ✓		
4) Steering ✓		
5) Brake ✓		

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 10-16-12

Vehicle # 7106 Operator Lee

Mileage 275845

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn		
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil	✓	
2) Coolant	✓	
3) Transmission	✓	
4) Steering	✓	
5) Brake	✓	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 10-15-12

Vehicle # 7106 Operator B Whitman Mileage 275479

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✗	✓
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil		
2) Coolant	✓	
3) Transmission		
4) Steering		
5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks: Rock chips

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 10-12-12

Vehicle # 7106 Operator Scott S Mileage 27514

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid	✓	X
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil ✓		
2) Coolant ✓		
3) Transmission ✓		
4) Steering ✓		
5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks: one wiper not working
Will Inform Jakima Transit.

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 10-10-12

Vehicle # 7106

Operator Scott S

Mileage 274474

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

*274748
41.9*

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil	✓	
2) Coolant	✓	
3) Transmission	✓	
4) Steering	✓	
5) Brake	✓	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

All Inspections good

HopeSource Pre-Trip Inspection Report

Date: 10-9-12

Vehicle # 7106 Operator Scott S Mileage 274377

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil ✓		
2) Coolant ✓		
3) Transmission ✓		
4) Steering ✓		
5) Brake ✓		

Mechanical Defect Report

Defect # (see above) _____

Remarks: _____

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

All checks good

AW

HopeSource Pre-Trip Inspection Report

Date: 10-8-12

Vehicle # 7106 Operator Lee

Mileage 274099

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil	✓	
2) Coolant	✓	
3) Transmission	✓	
4) Steering	✓	
5) Brake	✓	

*274,329
40.6*

Mechanical Defect Report

Defect # (see above) _____

Remarks: _____

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 10-5-12

Vehicle # 7106 Operator Scott S Mileage 273735

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	✓		• Radio/Cell Phone	✓	
• Interior Lights	✓		• Brakes	✓	
• Passenger Seat Condition	✓		• Parking Brake	✓	
• Emergency Equipment	✓		• Windshield	✓	
1) First Aid Kit	✓		• Headlights, Signals, 4-Ways	✓	
2) Fire Extinguisher	✓		• Tire/Wheel Condition	✓	
3) Reflections	✓		• Lug Nut Tightness	✓	
4) Strap Cutter	✓		• Body Condition	✓	
• Passenger Door Operations	✓		• Cycle W/C Lift	✓	
• Windshield	✓		• W/C Tiedowns & Accessories	✓	
Wipers/Washers & Fluid					
• Fans/Defrosters	✓		• Schedules	✓	
• Horn	✓		• Customer Service Forms	✓	
• Driver Seat & Belt	✓		• Farebox	✓	
• Mirrors	✓		• Fluids	✓	
			1) Oil ✓		
			2) Coolant ✓		
			3) Transmission ✓		
			4) Steering ✓		
			5) Brake ✓		

Mechanical Defect Report

Defect # (see above) _____

Remarks: MCI Pretrip Form.

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

Handwritten signature/initials

HopeSource Pre-Trip Inspection Report

Date: 10-3-12

Vehicle # 7106 Operator Scott S Mileage 273354

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil ✓		
2) Coolant ✓		
3) Transmission ✓		
4) Steering ✓		
5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 10-2-12

Vehicle # 7106

Operator R. Whitman

Mileage 272992

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield		✓
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil		
2) Coolant	✓	
3) Transmission		
4) Steering		
5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks: Rock chips in windshields

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

AW

HopeSource Pre-Trip Inspection Report

Date: 10-1-12

Vehicle # 7106 Operator Lee

Mileage 272717

	Ok	Defect
• Fluid Leaks Under Bus	/	
• Interior Lights	/	
• Passenger Seat Condition	/	
• Emergency Equipment	/	
1) First Aid Kit	/	
2) Fire Extinguisher	/	
3) Reflections	/	
4) Strap Cutter	/	
• Passenger Door Operations	/	
• Windshield	/	
Wipers/Washers & Fluid	/	
• Fans/Defrosters	/	
• Horn	/	
• Driver Seat & Belt	/	
• Mirrors	/	

	Ok	Defect
• Radio/Cell Phone	/	
• Brakes	/	
• Parking Brake	/	
• Windshield	/	X
• Headlights, Signals, 4-Ways	/	
• Tire/Wheel Condition	/	
• Lug Nut Tightness	/	
• Body Condition	/	
• Cycle W/C Lift	/	
• W/C Tiedowns & Accessories	/	
• Schedules	/	
• Customer Service Forms	/	
• Farebox	/	
• Fluids	/	X X
1) Oil	/	
2) Coolant	/	
3) Transmission	/	
4) Steering	/	
5) Brake	/	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Rock Chip

Small oil leak bottom of motor near belts -

is not spraying out - slow leak -

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 2-28-12

Vehicle # 7106 Operator Bushman Mileage 272617

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	✓
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil		
2) Coolant	✓	
3) Transmission		
4) Steering		
5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks: Rock chip in windshield

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____

Repaired By: _____

Driver Reviewing Inspection: _____

Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 9-26-12

Vehicle # 7106 Operator Lee Mileage 272240

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield	✓	
Wipers/Washers & Fluid		✗
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	✗
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil	✓	
2) Coolant	✓	
3) Transmission	✓	
4) Steering	✓	
5) Brake	✓	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

✗ Rock chips

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 9-25-12

Vehicle # 7106 Operator Bushman Mileage 271960

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield		
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield		✓
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil		
2) Coolant		
3) Transmission		
4) Steering		
5) Brake	✓	

Mechanical Defect Report

Defect # (see above) _____

Remarks: Rock chips in windshield

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

BW

HopeSource Pre-Trip Inspection Report

Date: 9-20-2012

Vehicle # 7106 Operator Rowlance Mileage 271555

	Ok	Defect		Ok	Defect
• Fluid Leaks Under Bus	✓		• Radio/Cell Phone	✓	
• Interior Lights	✓		• Brakes	✓	
• Passenger Seat Condition	✓		• Parking Brake	✓	
• Emergency Equipment	✓		• Windshield	✓	
1) First Aid Kit	✓		• Headlights, Signals, 4-Ways	✓	
2) Fire Extinguisher	✓		• Tire/Wheel Condition	✓	
3) Reflections	✓		• Lug Nut Tightness	✓	
4) Strap Cutter	✓		• Body Condition	✓	
• Passenger Door Operations	✓		• Cycle W/C Lift	✓	
• Windshield	✓		• W/C Tiedowns & Accessories	✓	
Wipers/Washers & Fluid	✓				
• Fans/Defrosters	✓		• Schedules	✓	
• Horn	✓		• Customer Service Forms	✓	
• Driver Seat & Belt	✓		• Farebox	✓	
• Mirrors	✓		• Fluids	✓	
			1) Oil	✓	
			2) Coolant		
			3) Transmission		
			4) Steering		
			5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks: _____

Fuel gauge isn't working

Maintenance Disposition

Work Order # _____

Repairs Made _____

DRIVERS Adv. TO FUEL AT END
of each shift until Bus is in for service!
AND issue can be addressed. BOB R. [Signature]

Date Completed _____

Repaired By: _____

Driver Reviewing Inspection: _____

Date: _____

MCI INSPECTION FORM ON REVERSE

[Signature]

HopeSource Pre-Trip Inspection Report

Date: 9-19-12

Vehicle # 7106 Operator Tom Mace

Mileage 271288

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield		
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil		
2) Coolant		
3) Transmission		
4) Steering		
5) Brake		

Mechanical Defect Report

Defect # (see above) _____

Remarks: _____

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

AW ✓

HopeSource Pre-Trip Inspection Report

Date: 9-18-2012

Vehicle # 7106 Operator John Mace Mileage 271195

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield		
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil —		
2) Coolant —	✓	
3) Transmission —		
4) Steering —		
5) Brake —		

Mechanical Defect Report

Defect # (see above) _____

Remarks:

Maintenance Disposition

Work Order # _____

Repairs Made

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

HopeSource Pre-Trip Inspection Report

Date: 9-17-2012

Vehicle # 27106 Operator Ron Mac Mileage 271103

	Ok	Defect
• Fluid Leaks Under Bus	✓	
• Interior Lights	✓	
• Passenger Seat Condition	✓	
• Emergency Equipment	✓	
1) First Aid Kit	✓	
2) Fire Extinguisher	✓	
3) Reflections	✓	
4) Strap Cutter	✓	
• Passenger Door Operations	✓	
• Windshield		
Wipers/Washers & Fluid	✓	
• Fans/Defrosters	✓	
• Horn	✓	
• Driver Seat & Belt	✓	
• Mirrors	✓	

	Ok	Defect
• Radio/Cell Phone	✓	
• Brakes	✓	
• Parking Brake	✓	
• Windshield	✓	
• Headlights, Signals, 4-Ways	✓	
• Tire/Wheel Condition	✓	
• Lug Nut Tightness	✓	
• Body Condition	✓	
• Cycle W/C Lift	✓	
• W/C Tiedowns & Accessories	✓	
• Schedules	✓	
• Customer Service Forms	✓	
• Farebox	✓	
• Fluids	✓	
1) Oil	✓	
2) Coolant	✓	
3) Transmission	✓	
4) Steering	✓	
5) Brake	✓	

Mechanical Defect Report

Defect # (see above) _____

Remarks: driver window 4 rock chips

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

271,195
100.9AL

[Handwritten signature]

HopeSource Pre-Trip Inspection Report

Date: 9-14-12

Vehicle # 7106 Operator Lee

Mileage 270890

	Ok	Defect
• Fluid Leaks Under Bus	/	
• Interior Lights	/	
• Passenger Seat Condition	/	
• Emergency Equipment	/	
1) First Aid Kit	/	
2) Fire Extinguisher	/	
3) Reflections	/	
4) Strap Cutter	/	
• Passenger Door Operations	/	
• Windshield		
Wipers/Washers & Fluid	/	
• Fans/Defrosters	/	
• Horn	/	
• Driver Seat & Belt	/	
• Mirrors	/	

	Ok	Defect
• Radio/Cell Phone	NA	
• Brakes	-	
• Parking Brake	-	
• Windshield		X
• Headlights, Signals, 4-Ways		
• Tire/Wheel Condition	-	
• Lug Nut Tightness	-	
• Body Condition	-	
• Cycle W/C Lift	-	
• W/C Tiedowns & Accessories	-	
• Schedules	-	
• Customer Service Forms	-	
• Farebox	-	
• Fluids	-	
1) Oil	-	
2) Coolant	-	
3) Transmission	-	
4) Steering	-	
5) Brake	-	

Mechanical Defect Report

Defect # (see above) _____

Remarks:

* Rock chips in drivers side of windshield.

Maintenance Disposition

Work Order # _____

Repairs Made _____

Date Completed _____ Repaired By: _____

Driver Reviewing Inspection: _____ Date: _____

MCI INSPECTION FORM ON REVERSE

